

Furukawa Robert

From: Webb, Paul A CIV <[REDACTED]>
Sent: Tuesday, January 10, 2017 2:04 PM
To: Furukawa Robert
Subject: RE: El Faro LKP
Attachments: Inmarsat C distress_ Distress info EL FARO, 48NM East of San Salvador.pdf

Jon,

The 23-16.8N 073-28.8W position is entered in to MILSE has the primary location. In the email that [REDACTED] sent to D7 the first position listed is John Lawrence's position from his notes, from the phonecon with Davison. The MARLINK position is the one that it looks like D7 used that was then incorrectly converted and is the outlier. This is because it was the "Distress Information Sheet" received by LANTArea had the position as 23.28N 73.48W. SAROPS or the OU at D7 converted it to 23-16.8N 073-28.8W. That was the initial position used. Off by about 23 miles. Note that SAROPS will assume a position with a decimal point is 10th of whatever is before it (in this case degrees and change it to Degrees and Minutes). It will also change positions where DD-MM-SS.SS to DD-MM.MM.

Cheers,
Paul

-----Original Message-----

From: Furukawa Robert [mailto:[REDACTED]]
Sent: Tuesday, January 10, 2017 7:39 AM
To: Webb, Paul A CIV
Subject: [Non-DoD Source] El Faro LKP

Paul,

Weren't you saying something about the El Faro's LKP from the DPA's phone call of 23-26.3N, 073-51.6W getting messed up by the D7CC?

Do you know what happened?

Best regards,

R. Jon Furukawa